







COMBINATION METER

HOW TO PROCEED WITH TROUBLESHOOTING

05DKF-01

1	Vehicle Brought to Workshop
	
2	Customer Problem Analysis (See page 05-588)
	
3	Problem Symptom Confirmation (See page 05-600)
	
4	Circuit Inspection (See page 05-601 to 05-633)
	
5	Repair or Replace
	
6	Confirmation Test
	
7	End