


AIR CONDITIONING AMPLIFIER ASSY

55126-01

REPLACEMENT

1. REMOVE HEATER CONTROL KNOB (W/ RADIO)(See page 55-25)
2. REMOVE INSTRUMENT CLUSTER FINISH PANEL SUB-ASSY CTR (W/ RADIO)
(See page 71-12)
3. REMOVE RADIO RECEIVER ASSY (W/ RADIO)(See page 67-6)



4. REMOVE AIR CONDITIONING AMPLIFIER ASSY
 - (a) Disconnect the connector.
 - (b) Remove the 2 screws and air conditioning amplifier assy.