

LIGHTING SYSTEM

650VC-01

PRECAUTION

1. PRECAUTION FOR HEADLIGHT BULB REPLACEMENT

- (a) If the surface halogen lamp (headlamp) is coated with oil, lamp service life is shortened because of the heat generated when the lamp is on.
- (b) Since the internal pressure of the halogen lamp bulb (headlamp) is high, handle carefully. It may explode if dropped.
- (c) Try not to touch the lens with your fingers when changing the lamp because it could result in a dirty or moist lens. Always have the replacement bulb prepared before starting the installation.
- (d) Always replace the bulb with one of the same wattage.
- (e) In order to avoid a cloudy lens or water.
- (f) In order to avoid a cloudy lens or leakage, firmly reinstall the socket after bulb replacement.